


Side Cap Layout

options 1 - 6



Moulding Sidecap Display Installation Instructions

Total Moulding Package Includes:

Three Boxes:

Box One Contains:

Two Sign Headers with metal hanging brackets and screws

Box Two Contains:

One Sample Board with 2 metal hanging brackets and screws.

Box Three Contains:



One Project Board with 2 metal hanging brackets and screws.

Tools Needed:

Screw Gun with 5/16" Nut Driver

Tape Measure

Cleaning Cloth




Step 1. Remove 24" promotion Extrusion. Then Install top, middle and bottom brackets at the heights shown above. Secure to racking with the 6 enclosed self drilling screws. (two screws per bracket)

Step 2. Lifting the display carefully, place top mounting bracket onto the top hanging bracket as shown. (Make sure bottom bracket is also over bottom hanging bracket).



Step 3. Hang Headers on top brackets. Then secure with screw as in step 4.



Step 4. Secure displays to top and bottom bracket with 1 self drilling screw in the middle of each (three) brackets as shown.

Note: See page two for proper layout of finished displays.

Moulding Sidecap Display Installation Instructions



In Stock Moulding Display



Moulding Project Sidecap



Both Displays Installed in Store

36"" Side cap Hanging Instructions

The best method for the 36" deep end caps will be to mount the bar using the hooks to the front post (aisle side) of the end cap.

- 1) Secure the bar to the front post using self tapping screws.
- 2) Level the bar across to the back post (flue space side) of the end cap.
- 3) Secure the bar to the back post using self tapping screws.
- 4) Trim the hanger hardware using a hack saw to three inches smaller than the space between the posts on flue space side.
- 5) Hang the board and secure from the back using self tapping screws per the original instructions.

48" Side cap hang instructions

The best method for the 48" deep end caps will be to secure a 1/4" thick by 48" long piece of flat slotted steel (typically found in D25, used to secure garage door openers to the ceiling).

- 1) Mount the flat steel to the end cap using self tapping screws or nuts and bolts
- 2) Hang the board and secure from the back using self tapping screws per the original instructions.